



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
ASHFURLONG DRIVE	o/s 3	Dangerous	Stem decayed	Malus sp	Plant in existing pit o/s 3, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
ASHFURLONG DRIVE	O/S 20	Dying	Stem only left remaining, of	Malus sp	Plant in existing pit o/s 20, (same position as felled tree)	Crataegus laevigata 'Paul's Sc